




Montage / Mounting mini




Montage / Mounting maxi




Montage entre / Mounting between HEA200




Broche anti-passage / Bare pin BA9931
(trou à re-percer / hole to re-drill Ø15)




Montage / Mounting 45°



Montage / Mounting 90°



Montage / Mounting 135°



Montage / Mounting 180°

